

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref: C107605:J111804.077-20130515

Client: Hanson Construction Materials Pty Ltd

Attention: Martin Gear - Project Manager Aggregates

Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW

Report Date:	Wednesday 15 May 2013	Test Date:	Wednesday 15 May 2013
Sampling Procedure: Control		Sampled By:	Pumps On: SB
			Pumps Off: SB

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter Test Type No. Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during the scraping of top soil in the Infras	structure Area on the East Guyong
Quarry Site	

704				0.0/100	
731	Field Blank	-	-	0.0/100	-
2197	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0809 – 1547	1.00	0.0/100	< 0.01
1356	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0812 – 1551	1.00	0.0/100	< 0.01
3092	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0815 - 1553	1.00	0.0/100	< 0.01
3016	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0819 - 1556	1.00	0.0/100	< 0.01
845	Location 6 - Western Boundary of Proposed Quarry Pit (near Western Site Boundary) - On barbed wire fence	0832 - 1616	1.00	0.0/100	< 0.01
242	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0836 – 1620	1.00	0.0/100	< 0.01
2103	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0826 - 1604	1.00	0.0/100	< 0.01



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
3070	Location N1 – North of Work Area, (north of scraping area in IA) – On fencing post	0846 - 1607	1.00	0.0/100	< 0.01
3069	Location N2 – West of Work Area, (west of scraping area in IA) – On fencing post	0844 - 1609	1.00	0.0/100	< 0.01
436	Location N3 – South of Work Area, (south of scraping area in IA) – On fencing post	0841 - 1611	1.00	0.0/100	< 0.01
625	Location N4 – East of Work Area, (east of scraping area in IA) – On barbed wire fence	0858 – 1602	1.00	1.0/100	< 0.01
2230	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	0903 - 1629	1.00	1.0/100	< 0.01
Exposure monitoring during scraping works in IA					
2208	Joseph Pilkauskas (EODO Pty Ltd) – Scraper Operator	0855 - 1627	1.00	2.5/100	< 0.01

Bimi Bracer 1d

Approved Counter & Signatory: Simon Butterfield




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station