

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:C107605:J111804 035-20130212Client:Hanson Construction Materials Pty LtdAttention:Martin Gear - Project Manager AggregatesJob Location:East Guyong Quarry, Mitchell Highway, East Guyong NSWReport Date:Tuesday 12 February 2013Test Date:Sampling Procedure:ControlSampled By:Pumps On:SBPumps Off:SB

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---------------	------------------------------	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during construction works (excavation & filling) for the new access road on the East Guyong Quarry Site

2232	Field Blank	_	_	0.0/100	_
2236	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0713 – XXXX	-	0.0/100	Voided*
2190	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0719 – 1617	1.00	0.0/100	< 0.01
2163	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0725 – 1652	1.00	1.0/100	< 0.01
2012	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0729 – 1650	1.00	0.0/100	< 0.01
2232	Location 6 - Western Boundary of Proposed Quarry Pit (near Western Site Boundary) - On barbed wire fence	0752 – 1629	1.00	0.0/100	< 0.01
1090	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0758 – 1632	1.00	0.0/100	< 0.01
2258	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0746 – 1636	1.00	0.0/100	< 0.01

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane

Practical Solutions



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
1046	Location N1 – North of Work Area, (approx. 15 metres north of new access road) – On fencing post	0737 – 1644	1.00	0.0/100	< 0.01	
737	Location N2 – West of Work Area (approx. 15 metres west of new access road) – On barbed wire fence	0740 – 1640	1.00	0.0/100	< 0.01	
2094	Location N3 – East of Work Area (approx. 15 metres east of new access road) – On barbed wire fence	0735 – 1646	1.00	0.0/100	< 0.01	
2129	Location N4 – South of Work Area (south end of new access road) – On barbed wire fence	0722 – 1618	1.00	0.0/100	< 0.01	
417	Location N5 – Southern Side of Mitchell Highway, Site Compound, Lunch Shed	0828 – 1613	1.00	1.0/100	< 0.01	
Exposure monitoring during excavation and filling works						
613	Marty Rookyard – Excavator Operator (EODO) (for new access road)	0813 – 1642	1.00	1.0/100	< 0.01	
937	Allan Galvin - Excavator Operator (EODO) (for new access road)	0820 – 1620	1.00	0.0/100	< 0.01	

Note: Filter No. 2236 is voided due to flow rate exceeding variation criteria (+/-10%).

Simi Bracery

Approved Counter and Signatory : Simon Butterfield




This document is issued in accordance with NATA's accreditation requirements.

Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station