

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref: C107605:J111804 037-20130214

Client: Hanson Construction Materials Pty Ltd

Attention: Martin Gear - Project Manager Aggregates

Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW

Report Date:	Thursday 14 February 2013	Test Date:	Thursday 14 February 2013		
Sampling Procedure: Control		Sampled By:	Pumps On: SB		
			Pumps Off: SB		

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---------------	------------------------------	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during construction works (excavation & filling) for the new access road on the East Guyong Quarry Site

1001	Field Blank	_	_	0.0/100	_
2232	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0738 – 1533	1.00	0.0/100	< 0.01
2094	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0743 – 1440	1.00	2.0/100	< 0.01
2163	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0753 – 1446	1.00	0.0/100	< 0.01
2129A	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0756 – 1448	1.00	0.0/100	< 0.01
937	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0819 – 1506	1.00	0.0/100	< 0.01
417	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0823 – 1509	1.00	0.0/100	< 0.01
2012	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0815 – 1502	1.00	0.0/100	< 0.01

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane

**Practical Solutions** 



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
1090	Location N1 – North of Work Area, (approx. 15 metres north of new access road) – On fencing post	0802 – 1453	1.00	0.0/100	< 0.01
2190	Location N2 – West of Work Area (approx. 15 metres west of new access road) – On barbed wire fence	0805 – 1455	1.00	0.0/100	< 0.01
2236	Location N3 – East of Work Area (approx. 15 metres east of new access road) – On barbed wire fence	0759 – 1451	1.00	0.0/100	< 0.01
613	Location N4 – South of Work Area (south end of new access road) – On barbed wire fence	0750 – 1438	1.00	0.0/100	< 0.01
2235	Location N5 – Southern Side of Mitchell Highway, Site Compound, Lunch Shed	0746 – 1443	1.00	2.0/100	< 0.01
Exposure monitoring during excavation and filling works					
2258	Marty Rookyard – Excavator Operator (EODO) (for new access road)	0810 – 1458	1.00	0.0/100	< 0.01
242	Allan Galvin - Excavator Operator (EODO) (for new access road)	0832 – 1520	1.00	3.5/100	< 0.01

Bimi Bruenfield

Approved Counter and Signatory : Simon Butterfield




This document is issued in accordance with NATA's accreditation requirements.

Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station