

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:C107605:J111804 038-20130218Client:Hanson Construction Materials Pty LtdAttention:Martin Gear - Project Manager AggregatesJob Location:East Guyong Quarry, Mitchell Highway, East Guyong NSWReport Date:Monday 18 February 2013Test Date:Sampling Procedure:ControlSampled By:Pumps Off: SB

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---------------	------------------------------	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during construction works (excavation & filling) for the new access road on the East Guyong Quarry Site

2224	Field Blank	-	_	0.0/100	_
230	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0945 – 1538	1.20	0.0/100	< 0.01
2035	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0958 – 1547	1.20	1.0/100	< 0.01
2185	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	1004 – 1605	1.20	0.0/100	< 0.01
2242	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	1008 – 1609	1.20	0.0/100	< 0.01
1310	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	1045 – 1655	1.20	0.0/100	< 0.01
2180	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	1050 – 1702	1.20	0.0/100	< 0.01
2134A	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	1034 – 1643	1.20	0.0/100	< 0.01

Practical Solutions



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
2210	Location N1 – North of Work Area, (approx. 15 metres north of new access road) – On fencing post	1025 – 1635	1.20	0.0/100	< 0.01	
1000	Location N2 – West of Work Area (approx. 15 metres west of new access road) – On barbed wire fence	1029 – 1617	1.20	0.0/100	< 0.01	
2105	Location N3 – East of Work Area (approx. 15 metres east of new access road) – On barbed wire fence	1021 – 1625	1.20	0.0/100	< 0.01	
446	Location N4 – South of Work Area (south end of new access road) – On barbed wire fence	0956 – 1544	1.20	0.0/100	< 0.01	
1015	Location N5 – Southern Side of Mitchell Highway, Site Compound, Lunch Shed	1000 – 1550	1.20	2.0/100	< 0.01	
Exposure monitoring during excavation and filling works						
304	Marty Rookyard - Excavator Operator (EODO) (for new access road)	1015 – 1627	1.20	1.0/100	< 0.01	
2105A	Bree Fradon – Grader Operator (EODO) (for new access road & southern side of Mitchell Highway)	0952 – 1600	1.20	5.0/100	< 0.01	

Bini Binenfield

Approved Counter and Signatory : Simon Butterfield




This document is issued in accordance with NATA's accreditation requirements.

Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station