

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:C107605:J111804 027-20130131Client:Hanson Construction Materials Pty LtdAttention:Martin Gear - Project Manager AggregatesJob Location:East Guyong Quarry, Mitchell Highway, East Guyong NSWReport Date:Thursday 31 January 2013Test Date:Sampling Procedure:ControlSampled By:Pumps On: SB<br/>Pumps Off: SB

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---------------	------------------------------	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during scraping / excavation of the topsoil for the new access road on the East Guyong Quarry Site

2027	Field Blank	_	_	0.0/100	_
229	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0744 – 1702	1.00	0.0/100	< 0.01
M011	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0853 – 1602	1.00	0.0/100	< 0.01
1223	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0844 – 1612	1.00	0.0/100	< 0.01
2124	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0848 – 1615	1.00	0.0/100	< 0.01
2104	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0751 – 1641	1.00	1.0/100	< 0.01
2242	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0758 – 1652	1.00	0.0/100	< 0.01
731	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0811 – 1634	1.00	1.0/100	< 0.01

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane

**Practical Solutions** 



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
2207	Location N1 – North of Work Area, (approx. 15 metres north of new access road) – On fencing post	0814 – 1626	1.00	0.0/100	< 0.01	
2160	Location N2 – West of Work Area (approx. 15 metres west of new access road) – On barbed wire fence	0820 – 1628	1.00	0.0/100	< 0.01	
242	Location N3 – East of Work Area (approx. 15 metres east of new access road) – On barbed wire fence	0826 – 1622	1.00	0.0/100	< 0.01	
647	Location N4 – South of Work Area (south end of new access road) – On barbed wire fence	0856 – 1604	1.00	0.0/100	< 0.01	
Exposure monitoring during scraping works						
2124A	Marty Rookyard – Excavator Operator (EODO)	0834 – 1631	1.00	1.0/100	< 0.01	
2234	John Willis – Excavator Operator (EODO)	0902 – 1608	1.00	1.0/100	< 0.01	

Bini Brandield

Approved Counter and Signatory : Simon Butterfield




This document is issued in accordance with NATA's accreditation requirements.

Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station