

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:C107605:J111804 047-20130304Client:Hanson Construction Materials Pty LtdAttention:Martin Gear - Project Manager AggregatesJob Location:East Guyong Quarry, Mitchell Highway, East Guyong NSWReport Date:Monday 4 March 2013Test Date:Sampling Procedure:ControlSampled By:Pumps On: SB
Pumps Off: SB

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
---------------	------------------------------	----------------------------------	---------------------------------	-------------------	------------------------

Control static monitoring during excavation works in the NW section of the Infrastructure Area (IA) and construction of the earth bund wall on the eastern side of the IA on the East Guyong Quarry Site

687	Field Blank	-	_	0.0/100	-
2124	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	1012 – 1615	1.20	4.0/100	< 0.01
1223	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	1015 – 1619	1.20	2.0/100	< 0.01
2074	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	1018 – 1621	1.20	0.0/100	< 0.01
2122	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	1021 – 1623	1.20	0.0/100	< 0.01
482	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	1100 – 1659	1.20	1.0/100	< 0.01
2172	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	1106 – 1701	1.20	3.0/100	< 0.01
2129A	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	1028 – 1630	1.20	1.0/100	< 0.01

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
2268	Location N1 – South of Work Area (NW section of Infrastructure Area) – On fence post	1038 – 1638	1.20	0.0/100	< 0.01	
911A	Location N2 – West of Work Area (NW section of Infrastructure Area) – On barbed wire fence	1041 – 1641	1.20	1.0/100	< 0.01	
2085	Location N3 – North of Work Area (NW section of Infrastructure Area) – On barbed wire fence	1032 – 1634	1.20	0.0/100	< 0.01	
2181	Location N4 – East of Work Area (NW section of Infrastructure Area) – On fence post	1035 – 1636	1.20	1.0/100	< 0.01	
2094	Location N5 – South East of Earth Bund Wall (Eastern Perimeter Fence of Infrastructure Area) – On barbed wire fence	1044 – 1644	1.20	3.0/100	< 0.01	
2031	Location N6 – North East of Earth Bund Wall (Eastern Perimeter Fence of Infrastructure Area) – On barbed wire fence	1047 – 1647	1.20	0.0/100	< 0.01	
Exposure monitoring during excavation and bund wall construction works						
206	John Willis – Excavator Operator (EODO) (Infrastructure Area)	1050 – 1651	1.20	1.0/100	< 0.01	
2217	Patrick Collins - Articulated Dump Truck Operator (EODO) (Infrastructure Area)	1054 – 1654	1.20	8.5/100	< 0.01	

Bini Brandield 6

Approved Counter and Signatory : Simon Butterfield




This document is issued in accordance with NATA's accreditation requirements.

Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station