

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.076-20130514			
Client:	Hanson Construction Materials Pty Lt	d		
Attention:	Martin Gear - Project Manager Aggr	egates		
Job Location:	East Guyong Quarry, Mitchell Highway, East Guyong NSW			
Report Date:	Tuesday 14 May 2013	Test Date:	Tuesday 14 May 2013	
Sampling Proc	edure: Control	Sampled By:	Pumps On: SB Pumps Off: SB	

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL

Control static monitoring during the scraping of top soil in the Infrastructure Area on the East Guyor	١g
Quarry Site	

3079	Field Blank	_	_	0.0/100	_
3014	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0929 – 1630	1.20	1.0/100	< 0.01
3068	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0934 – 1546	1.25	0.0/100	< 0.01
3012	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0937 - 1550	1.20	0.0/100	< 0.01
3022	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0941 - 1553	1.20	0.0/100	< 0.01
3058	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0953 - 1610	1.20	0.0/100	< 0.01
3077	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0958 – 1613	1.20	0.0/100	< 0.01
3024	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0946 - 1600	1.20	0.0/100	< 0.01

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane

**Practical Solutions** 



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
3032	Location N1 – North of Work Area, (north of scraping area) – On fencing post	1025 - 1602	1.20	0.0/100	< 0.01
3017	Location N2 – West of Work Area, (west of scraping area) – On fencing post	1023 - 1605	1.20	0.0/100	< 0.01
815	Location N3 – South of Work Area, (south of scraping area) – On fencing post	1019 - 1607	1.20	0.0/100	< 0.01
3008	Location N4 – East of Work Area, (east of scraping area) – On barbed wire fence	1029 – 1622	1.20	0.0/100	< 0.01
3059	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	1005 - 1625	1.20	1.0/100	< 0.01
Exposure monitoring during scraping works					
3060	John Willis (EODO Pty Ltd) – Excavator Operator	1027 - 1618	1.20	2.0/100	< 0.01

Bimi Bracer 1d

Approved Counter & Signatory: Simon Butterfield




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station