

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

Pumps Off: Pere Riini (Hanson)

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.086-20130531					
Client:	Hanson Construction Materials Pty Ltd					
Attention:	Martin Gear - Project Manager Aggr	egates				
Job Location:	b Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW					
Report Date:	Monday 2 June 2013	Test Date:	Friday 31 May 2013			
Sampling Procedure: Control		Sampled By:	Pumps On: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control static monitoring during the excavation of soil in the Infrastructure Area on the East Guyong Quarry Site							
3095	Field Blank	-	-	0.0/100	-		
2244	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0741 – 1403	1.00	0.0/100	< 0.01		
1032	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0744 – 1406	1.00	0.0/100	< 0.01		
3055	Location 4 - Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road - On barbed wire fence	0748 - 1409	1.00	0.0/100	< 0.01		
687	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0751 - 1413	1.00	0.0/100	< 0.01		
1077	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0755 - 1418	1.00	0.0/100	< 0.01		
3061	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0758 – 1421	1.00	0.0/100	< 0.01		
2136A	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0804 - 1425	1.00	0.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
2156	Location N1 – Northern Boundary Fence of Infrastructure Area	0807 - 1428	1.00	1.0/100	< 0.01
2213	Location N2 – Western Boundary Fence of Infrastructure Area	0810 - 1431	1.00	0.0/100	< 0.01
2227	Location N3 – Eastern Boundary Fence of Infrastructure Area	0817 - 1438	1.00	0.0/100	< 0.01
1251	Location N4 – Southern Boundary Fence of Infrastructure Area	0817 – 1434	1.00	1.0/100	< 0.01
2145A	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	0820 - 1441	1.00	2.0/100	< 0.01

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Noel Arnold & Associates Pty Ltd assume responsibility for the data collected.

Simi Braced

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station