

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.087-20130603					
Client:	Hanson Construction Materials Pty Ltd					
Attention:	Martin Gear - Project Manager Aggregates					
Job Location:	D Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW					
Report Date:	Wednesday 5 June 2013	Test Date:	Monday 3 June 2013			
Sampling Proc	cedure: Control	Sampled By:	Pumps On: Pere Riini (Hanson) Pumps Off: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control static monitoring during the excavation of soil in the Infrastructure Area on the East Guyong Quarry Site							
647	Field Blank	-	-	0.0/100	-		
453	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0752 – 1415	1.00	0.0/100	< 0.01		
3099	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0755 – 1418	1.00	0.0/100	< 0.01		
2178	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0758 - 1421	1.00	0.0/100	< 0.01		
2152A	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0801 - 1425	1.00	0.0/100	< 0.01		
1223	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0806 - 1431	1.00	0.0/100	< 0.01		
2115	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0809 – 1434	1.00	0.0/100	< 0.01		
3084	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0814 - 1440	1.00	0.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
940	Location N1 – Northern Boundary Fence of Infrastructure Area	0817 - 1443	1.00	0.0/100	< 0.01	
2143A	Location N2 – Western Boundary Fence of Infrastructure Area	0820 - 1446	1.00	0.0/100	< 0.01	
3089	Location N3 – Eastern Boundary Fence of Infrastructure Area	0827 - 1453	1.00	0.0/100	< 0.01	
3081	Location N4 – Southern Boundary Fence of Infrastructure Area	0823 – 1449	1.00	0.0/100	< 0.01	
2220	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	0830 - 1456	1.00	2.0/100	< 0.01	
Exposure monitoring during scraping works in IA						
2206	Excavator Operator (PC350 Excavator) - John Willis (EODO)	0830 - 1456	1.00	1.0/100	< 0.01	

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Noel Arnold & Associates Pty Ltd assume responsibility for the data collected.

Bim - Bracent

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station