

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.089-20130605				
Client:	Hanson Construction Materials Pty Ltd				
Attention:	Martin Gear - Project Manager Aggregates				
Job Location:	East Guyong Quarry, Mitchell Highway, East Guyong NSW				
Report Date:	Friday 7 June 2013	Test Date:	Wednesday 5 June 2013		
Sampling Procedure: Control		Sampled By:	Pumps On: SB Pumps Off: SB		

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control static monitoring during cutting and filling works in the Infrastructure Area on the East Guyong Quarry Site							
3087	Field Blank	-	-	0.0/100	-		
2137A	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0740 – 1430	1.00	0.0/100	< 0.01		
2119A	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0743 – 1436	1.00	0.0/100	< 0.01		
2101	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0746 - 1438	1.00	0.0/100	< 0.01		
3065	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0750 - 1441	1.00	0.0/100	< 0.01		
1243	Location 6 - Western Boundary of Proposed Quarry Pit (near Western Site Boundary) - On barbed wire fence	0840 - 1508	1.00	0.0/100	< 0.01		
3077	Location 8 - Western Boundary (near NW Corner) of Site - On barbed wire fence	0845 – 1511	1.00	0.0/100	< 0.01		
3090	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0910 - 1552	1.00	0.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
3015	Location N1 – Northern Boundary Fence of Infrastructure Area	0912 - 1458	1.00	0.0/100	< 0.01	
3024	Location N2 – Western Boundary Fence of Infrastructure Area	0849 - 1514	1.00	0.0/100	< 0.01	
1226	Location N3 – Eastern Boundary Fence of Infrastructure Area	0905 - 1446	1.00	0.0/100	< 0.01	
1005	Location N4 – Southern Boundary Fence of Infrastructure Area	0854 – 1517	1.00	0.5/100	< 0.01	
2170	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	0858 - 1521	1.00	0.0/100	< 0.01	
Exposure monitoring during cutting and filling works in IA						
2106	Excavator Operator (PC350 Excavator) - John Willis (EODO)	0937 - 1530	1.50	3.5/100	< 0.01	

Bimi Bracertie 1d

Approved Counter & Signatory: Simon Butterfield




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station