

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

Pumps Off: Pere Riini (Hanson)

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.090-20130606					
Client:	Hanson Construction Materials Pty Ltd					
Attention:	Martin Gear - Project Manager Aggr	egates				
Job Location:	n: East Guyong Quarry, Mitchell Highway, East Guyong NSW					
Report Date:	Friday 7 June 2013	Test Date:	Thursday 6 June 2013			
Sampling Procedure: Control		Sampled By:	Pumps On: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control static monitoring during the excavation of soil in the Infrastructure Area on the East Guyong Quarry Site							
1310	Field Blank	-	-	0.0/100	-		
3064	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0745 – 1345	1.00	0.0/100	< 0.01		
640	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0748 – 1348	1.00	0.0/100	< 0.01		
2262	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0752 - 1352	1.00	1.0/100	< 0.01		
2146A	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0755 - 1355	1.00	0.0/100	< 0.01		
2086	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0801 - 1400	1.00	0.0/100	< 0.01		
3045	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0804 – 1403	1.00	0.0/100	< 0.01		
1323	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0809 - 1408	1.00	1.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
2133A	Location N1 – Northern Boundary Fence of Infrastructure Area	0812 - 1411	1.00	0.0/100	< 0.01
3057	Location N2 – Western Boundary Fence of Infrastructure Area	0815 - 1414	1.00	0.0/100	< 0.01
1040	Location N3 – Eastern Boundary Fence of Infrastructure Area	0822 - 1421	1.00	1.0/100	< 0.01
3100	Location N4 – Southern Boundary Fence of Infrastructure Area	0818 – 1417	1.00	0.0/100	< 0.01
3088	Location N5 – Lunch Shed, Adjacent to New Access Road – On bench	0825 - 1424	1.00	0.0/100	< 0.01

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Noel Arnold & Associates Pty Ltd assume responsibility for the data collected.

Simi Braced

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station