

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.162-20131021					
Client:	Hanson Construction Materials Pty Ltd					
Attention:	Martin Gear - Project Manager Aggregates					
Job Location:	: East Guyong Quarry, Mitchell Highway, East Guyong NSW					
Report Date:	Thursday 24 October 2013	Test Date:	Monday 21 October 2013			
Sampling Proc	cedure: Control	Sampled By:	Pumps On: Pere Riini (Hanson) Pumps Off: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control/static monitoring during earthworks in the Infrastructure Area on the East Guyong Quarry Site							
167052	Field Blank	-	-	0.0/100	-		
167604	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0723 – 1421	1.00	1.0/100	< 0.01		
167491	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0726 – 1424	1.00	0.0/100	< 0.01		
167347	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0729 – 1427	1.00	0.0/100	< 0.01		
167667	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0732 – 1430	1.00	0.0/100	< 0.01		
167595	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0737 – 1433	1.00	0.0/100	< 0.01		
166991	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0740 – 1436	1.00	0.0/100	< 0.01		
167224	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0746 – 1447	1.00	1.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane

Practical Solutions



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
167610	Location N1 – Northern Boundary Fence of Infrastructure Area	0746 – 1450	1.00	0.0/100	< 0.01	
167004	Location N2 – Western Boundary Fence of Infrastructure Area	0758 – 1459	1.00	0.0/100	< 0.01	
167160	Location N3 – Eastern Boundary Fence of Infrastructure Area	0752 – 1453	1.00	1.0/100	< 0.01	
167151	Location N4 – Southern Boundary Fence of Infrastructure Area	0755 – 1459	1.00	2.0/100	< 0.01	
Exposure/personal monitoring during earthworks in IA						
166999	Excavator Operator – John Willis (EODO)	0804 – 1507	1.00	0.0/100	< 0.01	

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Noel Arnold & Associates Pty Ltd assume responsibility for the data collected.

- Bracent

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station