

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

## ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.164-20131023					
Client:	Hanson Construction Materials Pty Lt	d				
Attention:	Martin Gear - Project Manager Aggregates					
Job Location:	Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW					
Report Date:	Monday 28 October 2013	Test Date:	Wednesday 23 October 2013			
Sampling Proc	cedure: Control	Sampled By:	Pumps On: Pere Riini (Hanson) Pumps Off: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control/static monitoring during earthworks in the Infrastructure Area on the East Guyong Quarry Site							
210112	Field Blank	-	-	0.0/100	-		
215924	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0712 – 1401	1.00	0.0/100	< 0.01		
215933	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0715 – 1404	1.00	0.0/100	< 0.01		
210328	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0718 – 1407	1.00	0.0/100	< 0.01		
210249	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0721 – 1410	1.00	0.0/100	< 0.01		
215974	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0727 – 1416	1.00	0.0/100	< 0.01		
215945	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0730 – 1419	1.00	0.0/100	< 0.01		
210170	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0735 – 1425	1.00	0.0/100	< 0.01		

■ Melbourne ■ Sydney ■ Canberra ■ Brisbane



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
210165	Location N1 – Northern Boundary Fence of Infrastructure Area	0738 – 1428	1.00	1.0/100	< 0.01	
210297	Location N2 – Western Boundary Fence of Infrastructure Area	0749 – 1437	1.00	0.0/100	< 0.01	
215942	Location N3 – Eastern Boundary Fence of Infrastructure Area	0741 – 1431	1.00	2.0/100	< 0.01	
215935	Location N4 – Southern Boundary Fence of Infrastructure Area	0744 – 1434	1.00	0.0/100	< 0.01	
Exposure/personal monitoring during earthworks in IA						
216040	Excavator Operator – John Willis (EODO)	0753 – 1441	1.00	0.0/100	< 0.01	

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Noel Arnold & Associates Pty Ltd assume responsibility for the data collected.

- Bracent

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



## Figure 1 – Air Monitoring Location



\* East Guyong Quarry Weather Station