

# Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road,

North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811

Email: sydney@noel-arnold.com.au

www.noel-arnold.com.au

### ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref: C107605:J111804.179-20131113

Client: Hanson Construction Materials Pty Ltd

Attention: Martin Gear - Project Manager Aggregates

Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW

Report Date: Friday 15 November 2013 Test Date: Wednesday 12 November 2013

Sampling Procedure: Control Sampled By: Pumps On: Simon Butterfield

Pumps Off: Simon Butterfield

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2<sup>nd</sup> Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
Control/static monitoring during earthworks in the Infrastructure Area on the East Guyong Quarry Site						
163981	81 Field Blank		-	0.0/100	-	
166965	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0702 – 1407	1.00	0.0/100	< 0.01	
167159	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0705 – 1406	1.00	0.0/100	< 0.01	
167550	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0708 – 1409	1.00	0.0/100	< 0.01	
166997	Location 5 - Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary - On fencing post	0711 – 1412	1.00	1.0/100	< 0.01	
166969	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0717 – 1434	1.00	0.5/100	< 0.01	
166935	Location 8 - Western Boundary (near NW Corner) of Site - On barbed wire fence	0734 – 1439	1.00	0.0/100	< 0.01	
166971	Location 10 - Near Northern Boundary of Site (near NE Corner Site) - On fencing post	0725 – 1421	1.00	2.0/100	< 0.01	



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
167201	Location N1 - Northern Boundary Fence of Infrastructure Area	0728 – 1424	1.00	1.0/100	< 0.01
167633	Location N2 - Western Boundary Fence of Infrastructure Area	0820 – 1443	1.00	0.0/100	< 0.01
166993	Location N3 - Eastern Boundary Fence of Infrastructure Area	0731 – 1418	1.00	0.0/100	< 0.01
166922	Location N4 - Southern Boundary Fence of Infrastructure Area	0734 – 1431	1.00	0.0/100	< 0.01
Exposure/personal monitoring during earthworks in IA					
167618	Excavator Operator - Craig White (EODO)	0814 – 1428	1.00	2.0/100	< 0.01







Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



## Air Monitoring Sampling Plan East Guyong Quarry Site

Monitoring Date: 13th November 2013

708,824mE; 6301,587mN

### Legend

- X 1 Air monitoring locations
- Project Boundary
- Proposed Quarry Boundary
- Proposed Infrastructure Area Boundary

|--|

Location 10: 709,465mE; 6301,633mN

Location 1:	709,104mE; 6300,660mN	Location N1:	709,211mE; 6301,528mN
Location 3:	709,601mE; 6300,370mN	Location N2:	709,035mE; 6301,323mN
Location 4:	709,729mE; 6300,716mN	Location N3:	709,396mE; 6301,245mN
Location 5:	709,870mE; 6300,905mN	Location N4:	709,208mE; 6301,040mN
Location 6:	708,803mE; 6301,185mN		

#### Weather Conditions

Location 8:

Weather Conditions*				
General	Overcast - Fine	Wind Direction	Mostly NW	
Rainfall	0	Wind Speed	4 – 45 km/h	

<sup>\*</sup> East Guyong Quarry Weather Station

C107605:J111804.179-20131113 Page 3 of 3