

Risk Management Services

NOEL ARNOLD & ASSOCIATES PTY LTD A.C.N. 006 318 010 A.B.N. 76 006 318 010 Level 2, 11 Khartoum Road, North Ryde, NSW 2113 Australia Phone: (02) 9889 1800 Fax: (02) 9889 1811 Email: sydney@noel-arnold.com.au www.noel-arnold.com.au

ASBESTOS FIBRE AIR MONITORING REPORT

Our Ref:	C107605:J111804.185-20131121					
Client:	Hanson Construction Materials Pty Lt	td				
Attention:	Martin Gear - Project Manager Aggregates					
Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW						
Report Date:	Monday 25 November 2013	Test Date:	Thursday 21 November 2013			
Sampling Proc	cedure: Control	Sampled By:	Pumps On: Pere Riini (Hanson) Pumps Off: Pere Riini (Hanson)			

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] – Refer NAA Internal Laboratory Test Method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Control/static monitoring during earthworks in the Infrastructure Area on the East Guyong Quarry Site							
167619	Field Blank	_	_	0.0/100	-		
167616	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0721 – 1401	1.00	0.0/100	< 0.01		
167614	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0734 – 1404	1.00	1.0/100	< 0.01		
163989	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0737 – 1407	1.00	3.5/100	< 0.01		
167625	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0740 – 1410	1.00	0.0/100	< 0.01		
167639	Location 6 - Western Boundary of Proposed Quarry Pit (near Western Site Boundary) - On barbed wire fence	0745 – 1416	1.00	2.0/100	< 0.01		
163986	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0748 – 1419	1.00	0.0/100	< 0.01		
167641	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0754 – 1422	1.00	1.0/100	< 0.01		

Practical Solutions



Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL	
167654	Location N1 – Northern Boundary Fence of Infrastructure Area	0757 – 1425	1.00	0.0/100	< 0.01	
163990	Location N2 – Western Boundary Fence of Infrastructure Area	0807 – 1436	1.00	0.0/100	< 0.01	
167640	Location N3 – Eastern Boundary Fence of Infrastructure Area	0801 – 1428	1.00	0.0/100	< 0.01	
163987	Location N4 – Southern Boundary Fence of Infrastructure Area	0804 – 1433	1.00	1.0/100	< 0.01	
Exposure/personal monitoring during earthworks in IA						
167644	Padfoot Roller Operator – John Willis (EODO)	0812 – 1442	1.00	0.0/100	< 0.01	

Simi Bracer Lal_

APPROVED COUNTER & SIGNATORY: SIMON BUTTERFIELD




Accredited for compliance with ISO/IEC 17025. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

This document shall not be reproduced, except in full.



Figure 1 – Air Monitoring Location



* East Guyong Quarry Weather Station