

Greencap-NAA Pty Ltd ABN: 76 006 318 010 Level 2 / 11 Khartoum Road North Ryde NSW 2113 Australia P: (02) 9889 1800 F: (02) 9889 1811 www.greencap.com.au

## Asbestos Fibre Air Monitoring Report

Our Ref: C107605:SO2002930.002-20161004
Client: Hanson Construction Materials Pty Ltd
Client Address: Locked Bag 5260, Parramatta NSW 2124

Attention: Pere Riini - Quarry Manager

Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW

Report Date: Thursday, 13 October 2016
Test Date: Tuesday, 4 October 2016

Sampling Type: Control

Sampled By: Pumps On: Pere Riini (Hanson)

Pumps Off: Pere Riini (Hanson)

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] and as described in supplementary work instruction in-house method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL
Asbestos background – Background asbestos air monitoring throughout various locations across the site.					
C0005 39502	Field Blank	-	-	0.0/100	-
C0005 39491	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0714 – 1501	1.00	1.0/100	< 0.01
C0005 39429	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0719 – 1509	1.00	0.0/100	< 0.01
C0005 39495	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0724 – 1514	1.00	0.0/100	< 0.01
C0005 39471	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0729 – 1519	1.00	1.0/100	< 0.01
C0005 39501	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0738 – 1524	1.00	0.0/100	< 0.01
C0005 39443	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0744 – 1530	1.00	0.0/100	< 0.01
C0005 39511	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0751 – 1537	1.00	0.0/100	< 0.01

Note: In accordance with p26 of NOHSC 3003 (2005), if the fibre count is less than 10 fibres/100 graticule areas, then the count is not considered significantly above that of background.

C107605:SO2002930.002-20161004



Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Greencap – NAA Pty Ltd assume responsibility for the data collected.

me ou

Approved Counter: Simon Day



Approved Signatory: Simon Day



This document shall not be reproduced, except in full.

Accredited for compliance with ISO/IEC 17025 Testing. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.



Figure 1 – Air Monitoring Location



