

Greencap-NAA Pty Ltd ABN: 76 006 318 010 Level 2 / 11 Khartoum Road North Ryde NSW 2113 Australia P: (02) 9889 1800 F: (02) 9889 1811 www.greencap.com.au

Asbestos Fibre Air Monitoring Report

Our Ref:	C107605:SO2002930.001-20160929
Client:	Hanson Construction Materials Pty Ltd
Client Address:	Locked Bag 5260, Parramatta NSW 2124
Attention:	Pere Riini - Quarry Manager
Job Location:	East Guyong Quarry, Mitchell Highway, East Guyong NSW
Report Date:	Thursday, 13 October 2016
Test Date:	Thursday, 29 September 2016
Sampling Type:	Control
Sampled By:	Pumps On: Pere Riini (Hanson)
	Pumps Off: Pere Riini (Hanson)

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] and as described in supplementary work instruction in-house method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
Asbestos background – Background asbestos air monitoring throughout various locations across the site.							
C0005 39483	Field Blank	_	-	0.0/100	_		
C0005 39447	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0722 – 1444	1.00	0.0/100	< 0.01		
C0005 39497	Location 3 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0729 – 1449	1.00	3.0/100	< 0.01		
C0005 39523	Location 4 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0735 – 1453	1.00	0.0/100	< 0.01		
C0005 39514	Location 5 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0741 – 1501	1.00	1.0/100	< 0.01		
C0005 39488	Location 6 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0749 – 1506	1.00	0.0/100	< 0.01		
C0005 39486	Location 8 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0755 – 1511	1.00	1.0/100	< 0.01		
C0005 39512	Location 10 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0801 – 1520	1.00	1.0/100	< 0.01		

Note: In accordance with p26 of NOHSC 3003 (2005), if the fibre count is less than 10 fibres/100 graticule areas, then the count is not considered significantly above that of background.

October 2016



Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Greencap – NAA Pty Ltd assume responsibility for the data collected.

Approved Counter: Simon Day

Approved Signatory: Simon Day




This document shall not be reproduced, except in full.


Accredited for compliance with ISO/IEC 17025 -Testing. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.









Wind Direction

Wind Speed

Overcast-Fine

General

Rainfall