

Greencap Pty Ltd ABN: 76 006 318 010 Level 2 / 11 Khartoum Road North Ryde NSW 2113 Australia P: (02) 9889 1800 www.greencap.com.au

Riini (Hanson)

Asbestos Fibre Air Monitoring Report

		•
Our Ref:	C107605:SO2006056.002-20171003	
Client:	Hanson Construction Materials Pty Ltd	
Client Address:	Locked Bag 5260, Parramatta NSW 2124	
Attention:	Pere Riini – Quarry Manager	
Job Location:	East Guyong Quarry, Mitchell Highway, Ea	st Guyong NSW
Report Date:	Tuesday, 10 October 2017	
Analysis Date:	Monday, 9 October 2017	
Monitoring Date:	Tuesday, 3 October 2017	
Sampling Type:	Control & Exposure	
Sampled By:	Pumps On: Pere Riini (Hanson)	Pumps Off: Pere
Location of Analysis:	Khartoum Rd North Ryde Laboratory	

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] and as described in supplementary work instruction in-house method NALAB 301.

Filter No.	Test Type Sample Location	Sample Period Start-Finish	Average Flow Rate (L/min)	Fibres/ Fields	Result(s) Fibres/mL		
C0011 79326	Field Blank	-	-	0.0/100	-		
Asbestos background – Background asbestos air monitoring throughout various locations across the site							
C0011 79315	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South site boundary – On barbed wire fence	0657 – 1505	1.00	0.5/100	< 0.01		
C0011 79309	Location 2 – Near Southern Boundary (SE corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South site boundary – On barbed wire fence	0705 – 1512	1.00	1.0/100	< 0.01		
C0011 79308	Location 3 – Near Eastern Boundary (near SE corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0711 – 1519	1.00	0.0/100	< 0.01		
C0011 79332	Location 4 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0718 – 1525	1.00	0.0/100	< 0.01		
C0011 79653	Location 5 – Western Boundary of Proposed Quarry Pit (near Western site boundary) – On barbed wire fence	0723 – 1531	1.00	0.0/100	< 0.01		
C0011 79413	Location 6 – Western Boundary (near NW corner) of site – On barbed wire fence	0734 – 1537	1.00	0.0/100	< 0.01		
C0011 79330	Location 7 – Near Northern Boundary of site (near NE corner of site) – On fencing post	0740 – 1543	1.00	0.0/100	< 0.01		
C0011 79654	Personal – R. Chapman, Operator, 2 x 470 Excavator	0747 – 1555	1.00	0.0/100	< 0.01		

Note: In accordance with p26 of NOHSC 3003 (2005), if the fibre count is less than 10 fibres/100 graticule areas, then the count is not considered significantly above that of background.

October 2017



Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Greencap Pty Ltd assume responsibility for the data collected.

Approved Counter: Simon Day

Approved Signatory: Simon Day



This document shall not be reproduced, except in full. Accredited for compliance with ISO/IEC 17025 - Testing. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.





