

Greencap Pty Ltd ABN: 76 006 318 010 Level 2 / 11 Khartoum Road North Ryde NSW 2113 Australia T: 02 9889 1800

Asbestos Fibre Air Monitoring Report

Our Ref: C107605:SO2007865.002-20180604
Client: Hanson Construction Materials Pty Ltd
Client Address: Locked Bag 5260, Parramatta NSW 2124

Attention: Pere Riini - Quarry Manager

Job Location: East Guyong Quarry, Mitchell Highway, East Guyong NSW

Report Date: Tuesday, 12 June 2018
Analysis Date: Friday, 8 June 2018
Monitoring Date: Monday, 4 June 2018

Sampling Type: Control

Sampled By: Start: Pere Riini (Hanson) Finish: Pere Riini (Hanson)

Location of Analysis: Khartoum Rd North Ryde Laboratory

Method: Filters examined in accordance with Safe Work Australia's Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] and as described in supplementary work instruction in-house method LAB03.

Sample Filter No.	Test Type Sample Location	Sample Time Start-Finish	Sampling Rate (avg) (L/min)	Fibres/ Fields	Result(s) Fibres/mL
C003330992	Field Blank	_	_	0.0/100	_
Asbestos background – Asbestos air monitoring throughout various locations across the C0033 site					
C003331340	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South Site Boundary – On barbed wire fence	0646 – 1502	1.00	0.0/100	< 0.01
C003331360	Location 2 – Near Southern Boundary (SE Corner) of Site, Adjacent to New Access Road Entry (No. 3410) off Mitchell Highway, approx. 30 metres from South Site Boundary – On barbed wire fence	0652 – 1512	1.00	0.0/100	< 0.01
C003331151	Location 3 – Near Eastern Boundary (near SE Corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0659 – 1520	1.00	1.0/100	< 0.01
C003331222	Location 4 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0715– 1525	1.00	1.0/100	< 0.01
C003331367	Location 5 – Western Boundary of Proposed Quarry Pit (near Western Site Boundary) – On barbed wire fence	0724 – 1530	1.00	0.0/100	< 0.01
C003331246	Location 6 – Western Boundary (near NW Corner) of Site – On barbed wire fence	0724 – 1530	1.00	0.0/100	< 0.01
C003331082	Location 7 – Near Northern Boundary of Site (near NE Corner Site) – On fencing post	0736 - 1544	1.00	0.0/100	< 0.01

greencap.com.au



Note: In accordance with p26 of NOHSC 3003 (2005), if the fibre count is less than 10 fibres/100 graticule areas (fields), then the count is not considered significantly above that of background.

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Greencap Pty Ltd assume responsibility for the data collected.

Approved Counter: Lulu Scott

Approved Signatory: Lulu Scott



This document shall not be reproduced, except in full. Accredited for compliance with ISO/IEC 17025 - Testing. Corporate Site No. 5450, Site No. 3402 Sydney Laboratory. The results of the tests, calibrations and/or measurements included in this document are traceable to ACCREDITATION Australian/national standards.