

## Asbestos Fibre Air Monitoring Report


**Our Ref:** C107605:SO2006802.002-20180130  
**Client:** Hanson Construction Materials Pty Ltd  
**Client Address:** Locked Bag 5260, Parramatta NSW 2124  
**Attention:** Pere Riini – Quarry Manager  
**Job Location:** East Guyong Quarry, Mitchell Highway, East Guyong NSW  
**Report Date:** Wednesday, 7 February 2018  
**Analysis Date:** Wednesday, 7 February 2018  
**Monitoring Date:** Tuesday, 30 January 2018  
**Sampling Type:** Control & Exposure  
**Sampled By:** **Start:** Pere Riini (Hanson) **Finish:** Pere Riini (Hanson)  
**Location of Analysis:** Khartoum Rd North Ryde Laboratory  
**Licensed Asbestos Removal Contractor:** N/A **Notification No:** N/A

**Method:** Filters examined in accordance with Safe Work Australia’s Guidance Note on the Membrane Filter Method for the Estimation of Airborne Asbestos Fibres, 2nd Edition, 2005 [NOHSC:3003: (2005)] and as described in supplementary work instruction in-house method LAB03.


Sample Filter No.	Test Type Sample Location	Sample Time Start-Finish	Sampling Rate (avg) (L/min)	Fibres/ Fields	Result(s) Fibres/mL
C004853751	Field Blank	–	–	0.0/100	–
Asbestos background – Background asbestos air monitoring throughout various locations across the site					
C004853516	Location 1 – Near Southern Boundary of Site, Access Road to Residence (No.3472) off Mitchell Highway, approx. 120 metres North of South site boundary – On barbed wire fence	0640 – 1432	1.00	0.0/100	< 0.01
C004853454	Location 2 – Near Southern Boundary (SE corner) of Site, Adjacent to New Access Road Entry (No.3410) off Mitchell Highway, approx. 30 metres from South site boundary – On barbed wire fence	0651 – 1437	1.00	0.0/100	< 0.01
C004853410	Location 3 – Near Eastern Boundary (near SE corner) of Site, approx. 70 metres West of Shed, Access Road – On barbed wire fence	0657 – 1442	1.00	0.0/100	< 0.01
C004853495	Location 4 – Near Eastern Boundary (near Centre) of Site, approx. 50 metres West of East Site Boundary – On fencing post	0708 – 1450	1.00	0.0/100	< 0.01
C004853553	Location 5 – Western Boundary of Proposed Quarry Pit (near Western site boundary) – On barbed wire fence	0714 – 1456	1.00	0.0/100	< 0.01
C004853609	Location 6 – Western Boundary (near NW corner) of site – On barbed wire fence	0721 – 1502	1.00	0.0/100	< 0.01
C004853775	Location 7 – Near Northern Boundary of site (near NE corner of site) – On fencing post	0727 – 1508	1.00	0.0/100	< 0.01
C004853412	Personal – R. Chapman, PC450 Excavator	0735 – 1515	1.00	0.0/100	< 0.01

Note: In accordance with p26 of NOHSC:3003 (2005), if the fibre count is less than 10 fibres/100 graticule areas (fields), then the count is not considered significantly above that of background.

Note: Pere Riini of Hanson Construction Materials Pty Ltd has been formally trained as a third party for volume measurement. Greencap Pty Ltd assume responsibility for the data collected.



**Approved Counter:** Holly Kitamura  
**Asbestos Assessor Licence No.** LAA001127



**Approved Signatory:** Holly Kitamura  
**Asbestos Assessor Licence No.** LAA001127



This document shall not be reproduced, except in full.  
Accredited for compliance with ISO/IEC 17025 - Testing.  
Corporate Site No. 5450, Site No. 3402 Sydney Laboratory.  
The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

**Figure 1 – Air Monitoring Location**

