HANSON EPA LICENSE CONDITIONS - Blast Monitor Results

Date	Time	Blast Location	Blast #	Monitor Location	Air Blast dBL	Ground Vibration mm/sec	Comments	EPA contact
16.07.2020	1:27:00 PM	Floor 9	KQ20-27	Galeas 2nd Driveway	108.5dBL	0.4822	Blast KQ20-27 and KQ20-31 fired together	
03.07.2020	10:41:00 AM	Floor 8	KQ20-28	Galeas 2nd Driveway	110.7dBL	1.268		
10.07.2020	10:53:00 AM	Floor 11	KQ20-29	Galeas 2nd Driveway	103.9dBL	0.1354		
10.07.2020	10:51:00 AM	Floor 10	KQ20-30	Galeas 2nd Driveway	103.5dBL	0.7441		
16.07.2020	1:27:00 PM	Floor 9	KQ20-31	Galeas 2nd Driveway	108.5dBL	0.4822	Blast KQ20-27 and KQ20-31 fired together	
23.07.2020	9:51:00 AM	Floor 9	KQ20-32	Galeas 2nd Driveway	109.8dBL	1.021		
30.07.21020	10:16:00 AM	Floor 11	KQ20-33	Galeas 2nd Driveway	110.1dBL	0.4118		
06.08.2020	12:45:00 PM	Floor 7	KQ20-34	Galeas 2nd Driveway	107.3dBL	0.7863		
06.08.2020	12:47:00 PM	Floor 9	KQ20-35	Galeas 2nd Driveway	110.5dBL	1.165		
13.08.2020	10:04:41 AM	Floor 10	KQ20-36	Galeas 2nd Driveway	109.4dBL	0.5135		
18.08.2020	9:54:56 AM	Floor 10	KQ20-37	Galeas 2nd Driveway	109dBL	0.888		
20.08.2020	9:11:05 AM	Floor 5	KQ20-38	Galeas 2nd Driveway	112.3dBL	0.7744		
01.10.2020	11:25:68 AM	Floor 9	KQ20-39	Galeas 2nd Driveway	110.1dBL	0.756		
27.08.2020	9:52:50 AM	Floor 8	KQ20-40	Galeas 2nd Driveway	111.3dBL	1.144		
03.09.2020	9:42:00 AM	Floor 13	KQ20-41	Galeas 2nd Driveway	104.9dBL	0.9		
03.09.2020	9:44:00 AM	Floor 11	KQ20-42	Galeas 2nd Driveway	101.9dBL	0.25		
10.09.2020	10:53:57 AM	Floor 10	KQ20-43	Galeas 2nd Driveway	108.8dBL	0.3547		
17.09.2020	12:21:22 PM	Floor 9	KQ20-44	Galeas 2nd Driveway	103.5dBL	0.13		
18.11.2020	12:14:18PM	Floor 7	KQ20-45	Galeas 2nd Driveway	101.5dBL	0.5172		
24.09.2020	10:51:24 AM	Floor 9	KQ20-46	Galeas 2nd Driveway	105.6dBL	2.206		
01.10.2020	11:23:57 AM	Floor 11	KQ20-47	Galeas 2nd Driveway	101.5dBL	0.3924		
08.10.2020	10:23:09 AM	Floor 10	KQ20-48	Galeas 2nd Driveway	109dBL	0.6335		
15.10.2020	10:12:20 AM	Floor 11	KQ20-49	Galeas 2nd Driveway	112.7dBL	0.1409		
22.10.2020	10:53:13 AM	Floor 9	KQ20-50	Galeas 2nd Driveway	98.87dBL	0.9842		
22.10.2020	10:50:59 AM	Floor 11	KQ20-51	Galeas 2nd Driveway	104.8dBL	0.4653		
29.10.2020	10:38:43 AM	Floor 10	KQ20-52	Galeas 2nd Driveway	111.8dBL	1.22	Blast KQ20-52 & KQ20-53 fired together	
29.10.2020	10:38:43 AM	Floor 10	KQ20-53	Galeas 2nd Driveway	111.8dBL	1.22	Blast KQ20-52 & KQ20-53 fired together	
06.11.2020	9:33:33 AM	Floor 11	KQ20-54	Galeas 2nd Driveway	105.5dBL	0.7972		
19.11.2020	11:13:10 AM	Floor 9	KQ20-55	Galeas 2nd Driveway	103.5dBL	0.1488		
12.11.2020	9:29:45 AM	Floor 11	KQ20-56	Galeas 2nd Driveway	104.1dBL	0.2361		
24.11.2020	11:24:03 AM	Floor 2	KQ20-57	Galeas 2nd Driveway	99.7dBL	0.1583		
19.11.2020	11:17:05 AM	Floor 9	KQ20-58	Galeas 2nd Driveway	107dBL	0.4887		
25.11.2020	10:05:21 AM	Floor 11	KQ20-59	Galeas 2nd Driveway	100.4dBL	0.8275		