

**EAST GUYONG QUARRY COMMUNITY CONSULTATIVE COMMITTEE (EGQCCC)**

**MEETING NO. 02\_2016**

**Monday 21<sup>st</sup> November 2016**

**Minutes**

**LOCATION**

East Guyong Site Office  
3410 Mitchell Hwy  
East Guyong NSW 2798

**INVITED (EGQCCC)**

Mr	George Blackwell	(GB)	Chair
Ms	Heather Nicholls	(HN)	Cabonne Shire Council
Mr	Mark Holman	(MH)	Community Member – Dargo
Mr	Tony Gordon	(TG)	Community Member – Godolphin
Mr	Steve Harris	(SH)	Community Member – Fairview
Mr	Ryan Phillips	(RP)	Hanson
Mr	Pere Riini	(PR)	Hanson
Mr	Scott Cumberland	(SC)	Hanson

**APOLOGIES**

Mr	Mark Holman	(MH)	Community Member – Dargo
Mr	Tony Gordon	(TG)	Community Member – Godolphin
Mr	Scott Cumberland	(SC)	Hanson

**INVITED (OTHER)**

Nil

**MEETING START TIME**

5.10pm

ITEM NO	DISCUSSION POINT	ACTION/CLOSE OUT	DATE
<b>1.0</b>	<b>Welcome</b>		
1.1	(GB) - Welcome to the meeting.	No Action	21 Nov 16
<b>2.0</b>	<b>Apologies</b>		
2.1	Mr Mark Holman (MH) Mr Tony Gordon (TG) Mr Scott Cumberland (SC)	No Action	21 Nov 16
<b>3.0</b>	<b>Confirmation of the Minutes of the Previous Meeting</b>		
3.1	Minutes from the previous meeting were accepted	No Action	21 Nov 16
<b>4.0</b>	<b>Business Arising from the previous minutes</b>		
4.1	<ul style="list-style-type: none"> <li>Solar Bore is now in place, a poly pipe line will be excavated in the coming weeks.</li> </ul>	No Action	21 Nov 16
<b>5.0</b>	<b>East Guyong Quarry Operations update</b>		
5.1	(PR) presented updates on: <ul style="list-style-type: none"> <li>264,000 tonnes in sales to date</li> <li>14 blasts conducted to date with no issues or exceedances.</li> <li>The 2016 Independent Environmental Report &amp; Hanson's responses to the recommendations, has been conducted &amp; is now available on the East Guyong website.</li> <li>Site Solar Bore is in place, pipeline to be placed in due course.</li> <li>1 discharge recorded from the site water storage, all test results were within the approved limits.</li> <li>An internal nursery is being planned for the site; this will enable us to cultivate our own tube stock for future rehabilitation projects.</li> <li>Bore hole monitoring information was distributed.</li> </ul>	No Action	21 Nov 16
<b>6.0</b>	<b>General Business</b>		
6.1	<ul style="list-style-type: none"> <li>(SG) brought to the attention of the committee her concerns about structural damage occurring at her residence, possibly linked to quarry activity, the acting chair (HN) suggested the (SG) put her concerns in writing to the company as per the condition of consent process &amp; noting that upon formal receipt of her concerns the company may investigate further.</li> <li>As per PA_06_0193, Schedule 3 Condition 17, a structural inspection was conducted, it was found that the blasting was not at fault, however a blast monitor will be placed in the</li> </ul>	No Action	21 Nov 16

	<p>house yard to determine vibration levels for the next 5 blasts, 1 blast monitor reading has been conducted which was well within the approved limits level, Please note: There have been no exceedances to date.</p> <ul style="list-style-type: none"> <li>• A site tour was conducted with (GB), (HN), (SH), of the pit area sales area, the plant &amp; the Solar Bore.</li> </ul>		
<b>7.0</b>	<b>Next Meeting</b>		
7.1	Monday 08.05.2017	No Action	21 Nov 16

**MEETING CLOSED**

5.45pm