

EAST GUYONG QUARRY COMMUNITY CONSULTATIVE COMMITTEE (EGQCCC)

MEETING NO. 01_2017

Monday 15th May 2017

Minutes

LOCATION

East Guyong Site Office
3410 Mitchell Hwy
East Guyong NSW 2798

INVITED (EGQCCC)

Mr	George Blackwell	(GB)	Chair
Ms	Heather Nicholls	(HN)	Cabonne Shire Council
Mr	Mark Holman	(MH)	Community Member – Dargo
Mr	Tony Gordon	(TG)	Community Member – Godolphin
Mr	Steve Harris	(SH)	Community Member – Fairview
Mr	Ryan Phillips	(RP)	Hanson
Mr	Pere Riini	(PR)	Hanson
Mr	Scott Cumberland	(SC)	Hanson

APOLOGIES

Mr	Mark Holman	(MH)	Community Member – Dargo
Ms	Heather Nicholls	(HN)	Cabonne Shire Council
Mr	Scott Cumberland	(SC)	Hanson

INVITED (OTHER)

Nil

MEETING START TIME

5.15pm

ITEM NO	DISCUSSION POINT	ACTION/CLOSE OUT	DATE
1.0	Welcome		
1.1	(GB) - Welcome to the meeting.	No Action	15 May 17
2.0	Apologies		
2.1	Mr Mark Holman (MH) Ms Heather Nicholls (HN) Mr Scott Cumberland (SC)	No Action	15 May 17
3.0	Confirmation of the Minutes of the Previous Meeting		
3.1	Minutes from the previous meeting were accepted	No Action	15 May 17
4.0	Business Arising from the previous minutes		
4.1	<ul style="list-style-type: none"> • (SG) brought to the attention of the committee her concerns about structural damage occurring at her residence, possibly linked to quarry activity, the acting chair (HN) suggested the (SG) put her concerns in writing to the company as per the condition of consent process & noting that upon formal receipt of her concerns the company may investigate further. • As per PA_06_0193, Schedule 3 Condition 17, a structural inspection was conducted, it was found that the blasting could also be responsible for the new damage, however a blast monitor will be placed in the house yard to determine vibration levels for the next 5 blasts, 3 blast monitor readings have been conducted, there have been no exceedances to date. 	Actioned	15 May 17
5.0	East Guyong Quarry Operations update		
5.1	(PR) presented updates on: <ul style="list-style-type: none"> • 137,000 tonnes in sales to date (Calendar Year) • 6 blasts conducted to date with no issues or exceedances. • The 2016 Independent Environmental Report & Hanson's responses to the recommendations, has been conducted & is now available on the East Guyong website. • Site Solar Bore is in place, 401,000 litres, pumped thus far for 2017. • No water discharge from the sites water storage • No Dust exceedances to report from the site • An internal nursery is to be constructed, this will enable us to cultivate our own tube stock for future rehabilitation projects. • Bore hole monitoring information was distributed, showing a 	No Action	15 May 17

	<p>continuous flow to the North.</p> <ul style="list-style-type: none"> • New CCC Guidelines to be distributed to CCC members once obtained. (Attached) • Phase 1 of the 2017 Stripping campaign is complete approximately 100,000 ton was removed & placed into the visual amenities bunds. Phase 2 scheduled to commence October 2017. 	Actioned	15 May 17
6.0	General Business		
6.1	<ul style="list-style-type: none"> • (SH) Noticed Nightshift maintenance are leaving the front gate open whilst onsite when the quarry is unattended, (PR) to action. • Nightshift maintenance have been made aware of the importance of site security. • Site Visit to be implemented at next meeting 	Actioned	15 May 17
7.0	Next Meeting		
7.1	Monday 20.11.2017	No Action	15 May 17

MEETING CLOSED

6.00pm