



East Guyong Quarry EPA Licence Conditions – Public Monitoring Register

Date	Licence Number & Site Name	Monitoring Point	Test Type	Result	Comment	EPA Contact
09 April 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
12 May 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
11 June 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
10 July 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
12 Aug 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
09 Sept 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
09 Oct 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
09 Nov 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
01 Dec 2015	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin
	20190 – East Guyong Quarry	Point 1				M Corradin

Contact:

Pere Riini

Quarry Manager – East Guyong

Ph: 0438 244 437

Email: pere.riini@hanson.com.au