

EAST GUYONG QUARRY COMMUNITY CONSULTATIVE COMMITTEE (EGQCCC)

MEETING NO. 01_2019

Monday 20th of May 2019

Minutes

LOCATION

East Guyong Site Office
3410 Mitchell Hwy
East Guyong NSW 2798

INVITED (EGQCCC)

Mr	George Blackwell	(GB)	Chair
Ms	Heather Nicholls	(HN)	Cabonne Shire Council
Mr	Mark Holman	(MH)	Community Member – “Dargo”
Mr	Tony Gordon	(TG)	Community Member – “Godolphin”
Mr	Steve Harris	(SH)	Community Member – “Fairview”
Mr	Pere Riini	(PR)	Hanson

APOLOGIES

Mr	George Blackwell	(GB)	Chair
Mr	Tony Gordon	(TG)	Community Member – “Godolphin”

INVITED (OTHER)

Nil

MEETING START TIME

5.00pm

ITEM NO	DISCUSSION POINT	ACTION/CLOSE OUT	DATE
1.0	Welcome		
1.1	<ul style="list-style-type: none"> • (HN) – Chair - Welcome to the meeting. 	No Action	20 May 19
2.0	Apologies		
2.1	<ul style="list-style-type: none"> • Mr George Blackwell • Mr Tony Gordon 	No Action	20 May 19
3.0	Confirmation of the Minutes of the Previous Meeting		
3.1	<ul style="list-style-type: none"> • Minutes from the previous meeting were accepted 	No Action	20 May 19
4.0	Business Arising from the previous minutes		
4.1	<ul style="list-style-type: none"> • Nil 	No Action	20 May 19
5.0	East Guyong Quarry Operations update		
5.1	(PR) An update on the 2018/2019 - Operations <ul style="list-style-type: none"> • 2018: • Production/Sales/General • 381,000 tons in Production • 382,000 tons in Sales • 13 Blasts to date – No exceedances • No Water discharge from the sites water storage • No Dust exceedances to report from the site • No Noise Monitoring exceedances • No Natural Occurring Asbestos detected • 2019: • Jason Brown (0488 901 581) has been appointed Area Manager for Country west he will be based at East Guyong. • Production/Sales/General: • 92,000 tons in Production • 97,000 tons in Sales • 5 Blasts to date – No exceedances • The pit modification & the annual tons per year increase has been approved by the DPE, DA Mod distributed to CCC members, DA Mod also available on the Hanson East Guyong website. • The 2018 Annual Review has also been submitted to the DPE, this is also available on the Hanson East Guyong website, as part of the DA requirements all Management plans will be reviewed & completed within the 3 month time period. • Trees, shrubs & grass going well on the Southern amenities 	No Action	20 May 19

	<p>bund.</p> <ul style="list-style-type: none"> • 500 Trees & shrubs from the approved species list have been planted along the access road to replace lost tube stock, a bund, trees & shrubs have also been planted internally along the eastern wall of the pit as per DA requirements. • Site Solar Bore, 2Mg has been drawn thus far for 2019, the bore is only utilised during sunny daylight hours. • No Water discharge from the sites water storage (To date) • No Dust exceedances to report from the site (To date) • No Noise monitoring exceedances (To date) • No Natural Occurring Asbestos detected • Bore hole monitoring information was distributed, showing a continuous flow to the North. • 2019 Stripping campaign has been completed (South end of the pit) approx. 80,000 ton was removed. • Material from East Guyong is heading into Sydney at a steady flow. • The Met station has been repaired, it had sustained sensor damage. • Independent Environmental Audit scheduled for 2019 		
6.0	General Business		
6.1	<ul style="list-style-type: none"> • Nil 	No Action	20 May 19
7.0	Next Meeting		
7.1	<ul style="list-style-type: none"> • Monday 25.11.2019 	Actioned	20 May 19

MEETING CLOSED

5.50pm