

## HANSON EPA LICENSE CONDITIONS - Blast Monitor Results



Date	Time	Blast Location	Blast #	Monitor Location	Air Blast dBL	Ground Vibration mm/sec	Comments	EPA contact
27/02/2019	12:29pm	Floor 1	1901	Brandy Hill Dr - Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	97.3	0.9	Went very well no problems	
20/03/2019	11:59am	Floor 1	1902	Brandy Hill Dr- Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	104.8	0.4	Went very well no problems	
4/04/2019	12:16pm	Floor 1	1904	Brandy Hill Dr- Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	103.0	0.5	Went very well no problems	
23/04/2019	1:29pm	Floor 5	1903	Brandy Hill Dr- Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	104.1	0.4	Went very well no problems	
7/05/2019	11:00am	Floor 1	1905	Brandy Hill Dr- Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	nil trigger	nil trigger	Small shot, all went very well	
20/05/2019	10:32am	Floor 1	1906	Brandy Hill Dr- Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	106.1	0.3	Small production blast all went well	
27/05/2019	12:05pm	Floor 1	1907	Brandy Hill Drive - Closest Neighbour	nil trigger	nil trigger		
				Quarry Driveway	114.2	0.4	Small production blast all went well	