East Guyong Quarry EPA Licence Conditions – Public Monitoring Register 2020

Date - 2020	Licence Number & Site Name	Monitoring Point	Test Type	Result	Comment	EPA Contact
01.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
02.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
03.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
04.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
05.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
26.06.2020	20190 – East Guyong Quarry	Point 1	Lab results (water discharge W1 / sampling point 6)	pH – 8.4 Suspended Solids - <5 Oil & Grease - <5	Discharge – week 22 June 2020	J Scarborough
07.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
08.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
09.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
10.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
11.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
12.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough

Contact:
Chris Cooke
Quarry Manager – East Guyong
Ph: 0409 907 043 or 6368 7190
Email: chris.cooke@hanson.com.au