



**East Guyong Quarry EPA Licence Conditions – Public Monitoring Register 2020**

<b>Date - 2020</b>	<b>Licence Number &amp; Site Name</b>	<b>Monitoring Point</b>	<b>Test Type</b>	<b>Result</b>	<b>Comment</b>	<b>EPA Contact</b>
01.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
02.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
03.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
04.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
05.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
26.06.2020	20190 – East Guyong Quarry	Point 1	Lab results (water discharge W1 / sampling point 6)	pH – 8.4 Suspended Solids - <5 Oil & Grease - <5	Discharge – week 22 June 2020	J Scarborough
25.08.2020	20190 – East Guyong Quarry	Point 1	Lab results (water discharge W1 / sampling point 6)	pH – 7.9 Suspended Solids - <5 Oil & Grease - <5	Discharge – week 24 August 2020	J Scarborough
08.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
09.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
10.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
11.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough
12.2020	20190 – East Guyong Quarry	Point 1	-	0.0	No Discharge	J Scarborough

**Contact:**

**Chris Cooke**

**Quarry Manager – East Guyong**

**Ph: 0409 907 043 or 6368 7190**

**Email: [chris.cooke@hanson.com.au](mailto:chris.cooke@hanson.com.au)**