

13 June 2022

Mr Keith Horwood
Compliance and Enforcement Branch
Environmental Standards Division
Department of Environment
GPO BOX 787,
CANBERRA ACT 2601

Hanson Construction Materials Pty Ltd
ABN 90 009 679 734
PO BOX 187
Victoria Park WA 6979
35 Great Eastern Highway
Rivervale WA 6103
Tel +618 9311 8811
Fax +618 9472 3126
www.hanson.com.au

Dear Mr Horwood,

**LENNARD RD, GINGIN – ANNUAL COMPLIANCE REPORT
EPBC 2010/5620**

Hanson is pleased to provide the Annual Compliance report for Lennard Rd, Gingin. As per our letter to your department last year, we advise that clearing commenced on site on 15th March 2017. Condition 3 states:

3. 'Within three months of every 12 month anniversary of the commencement of the action, the person taking the action must publish a report on their website addressing compliance with each of the conditions of this approval. Documentary evidence providing proof of the date of publication and non-compliance with any of the conditions of this approval must be provided to the department at the same time as the compliance report is published.'

Please find a list of the conditions and compliance below:

Condition No.	Issue	Ongoing/ Completed/ Not yet applicable	Compliant/ Non-compliant
1	Commencement Notification	Completed	Compliant
2	Records	Ongoing	Compliant
3	Annual Compliance Report	Ongoing	Compliant
4	Clearing Area	Ongoing	Compliant
5	Banksia Woodlands Restoration Guide	Complete	Compliant
6	Restoration	Ongoing	Compliant
7	Conservation Covenant - Rehabilitation	Not Yet Applicable	Compliant
8	Conservation Covenant – Blue Shaded Area	Complete	Compliant
9	Topsoil	Ongoing	Compliant
10	Offset Contributions	Completed	Compliant
11	Substantial Commencement	Completed	Compliant
12	Independent Audit	Not Yet Applicable	Compliant

The table below illustrates the clearing and rehabilitation completed during the reporting period (15th March 2021 – 14th March 2022) to date.

	Clearing	Rehabilitation
2017	4.21 ha	0 ha
2018	0 ha*	0 ha
2019	3.02 ha*	2.49 ha
2020	3.16 ha	2.18 ha
2021	0 ha	0 ha
Total	10.39 ha	4.67 ha

*Due to updated aerial imagery being unavailable at the time of the previous report, this figure was amended to reflect the actual clearing completed.

Should you have any queries please don't hesitate to contact me on (08) 9311 8842 or via lisajane.hults@hanson.com.au.

Kind Regards,



Lisa-Jane Hults
Environmental Planning and Compliance Manager
Hanson Construction Materials